

## Annexure D

### BUILDING SAFETY CERTIFICATE

NO. 156 | CE | 2025-26

DATED: 29/05/2025

It is certified that **MANAS INTERNATIONAL SCHOOL** (name of the building or premises) at **MAJRI GRANT, HARIDWAR ROAD, DOIWALA, DEHRADUN** (address) is having block(s)/floors(s) as per details below:


Detail of block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. Of floor(s) in the block	GROUND	GROUND+1	GROUND +2	GROUND+3		

The building is owned/occupied by **MANAS INTERNATIONAL SCHOOL** (name of the institution) have complied with the building safety requirements in accordance with national building code rules, and verified by the officers concerned of **P.W.D., DEHRADUN** (name of department/ govt.) On **29/05/2025** (date of inspection) in the presence of **MR. NATTHI PRASAD AMOLI, MAJRI GRANT, HARIDWAR ROAD, DOIWALA, DEHRADUN** (name and address of the manager/secretary or his representative) and that the building/ premises is fit for occupancy for running school with effect from **30/05/2025** for a period of **2(TWO)** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Capacity of classroom should be kept as per classroom size.
2. Building should be got inspected after any natural disaster in area.
3. Fire safety and other safety standards should be as per prevailing guidelines of Fire Department.
4. Certificate is valid for above indicated period under normal circumstances.
5. In case of any defect observation in building due to internal or external reasons, inspection from authorized engineer must be conducted immediately.

Issued on **30/05/2025** at **12:00 PM** by **ASSISTANT ENGINEER, PWD**

- Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.

  
सहायक अभियन्ता  
निर्माण खण्ड लो०नि०वि०  
Signature with Seal देहरादून

Name: Shiva Kumar

Designation: Asst. Eng.

Name & Address Of Department/Office: P.W.D., Dehradun